

**Town of Randolph
Turner Free Library**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Approach and Entrance												
Exterior Access Route												
1	Main Entrance	Ext.		Exterior Access Route	Exterior		Cross slope > 1:50 (2.00%)	5.6%	Reduce cross slope to be no steeper than 1:50 (2.00%).	1	-	\$0
2	Near North Main Entrance	Ext.		Exterior Access Route	Sidewalk		Cross slope > 1:50 (2.00%)	3.6%	Reduce cross slope to be no steeper than 1:50 (2.00%).	1	-	\$0
3	Northwest Side Bike Rack	Ext.		Exterior Access Route	Exterior		Cross slope > 1:50 (2.00%)	4.0%	Reduce cross slope to be no steeper than 1:50 (2.00%).	1	-	\$0
4	Near Memorial Street Ramp to Main Entrance	Ext.		Exterior Access Route	71		Cross slope > 1:50 (2.00%)	5%	Reduce cross slope to be no steeper than 1:50 (2.00%).	1	-	\$0
5	North Main Street Entrance	Ext.		Exterior Access Route			Cross slope > 1:50 (2.00%) Running slope > 1:20 (5.00%)	3.4% 9.6%	Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5.00%).	1	-	\$0

**Town of Randolph
Turner Free Library**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
6	War Memorial	Ext.		Exterior Access Route	Exterior		Accessible route not provided	-	Ensure an accessible route is provided.	1	-	\$0
Off-Street Parking Lot or Garage												
7	Parking Lot	Ext		Off-Street Parking Lot or Garage	Visitor		Total # of designated accessible parking spaces Total # of designated van accessible spaces Running or cross slope at space > 1:50 (2.00%)	0 0 9.6% - -	Provide a van accessible parking space that is 96" wide min. with an access aisle that is 96" wide min. Provide identification signage with the International Symbol of Accessibility (ISA) and the designation "Van Accessible". Ensure the bottom of the sign is 60" min. above the ground and the top 96" max. above the ground. Reduce running or cross slope to be no steeper than 1:50 (2.00%) in all directions.	1	-	\$0
Exterior Ramp												
8	Main Entrance	Ext.		Exterior Ramp	N/A		Running slope > 1:12 (8.33%) Handrails not provided at both sides if rise is > 6"	11% -	Reduce running slope to be no steeper than 1:12 (8.33%). Provide handrails on both sides.	1	-	\$0
9	Memorial Street Ramp to Main Entrance	Ext.		Exterior Ramp	N/A		Edge protection < 4" high	-	Provide edge protection that prevents the passage of a 4" diameter sphere, where any portion of the sphere is within 4" of the finished floor or ground surface.	1	-	\$0
Exterior Stair												
10	War Memorial	Ext.		Exterior Stair	N/A		Handrail not provided on both sides	-	Provide a handrail on one side.	1	-	\$0

**Town of Randolph
Turner Free Library**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
11	Northwest Side Egress Near Memorial Parkway	Ext.		Exterior Stair	N/A		Handrail not provided on both sides	-	Provide a handrail on one side.	1	-	\$0
Entrance												
12	Northwest Side Bike Rack	Ext.		Entrance	Secondary Entrance		Directional sign to accessible entrance not provided	-	Provide a directional sign indicating the location of the nearest accessible entrance.	1	346	\$346
13	Main Entrance	Ext.		Entrance	Main Entrance		International Symbol of Accessibility not provided	-	Provide a sign with the International Symbol of Accessibility (ISA).	1	-	\$0
14	North Main Street Entrance	Ext.		Entrance	Secondary Entrance		International Symbol of Accessibility not provided	-	Provide a sign with the International Symbol of Accessibility (ISA).	1	-	\$0
Access to Goods and Services												
Means of Egress												
15	Main Entrance/Exit	1		Means of Egress	N/A		Tactile exit sign not provided Illuminated ISA symbol not provided (MAAB)	- -	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. When the exit sign is replaced with a new illuminated exit sign, provide an illuminated International Symbol of Accessibility (ISA).	1	432	\$432

**Town of Randolph
Turner Free Library**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
16	North Main Street Egress	2		Means of Egress	N/A		Tactile exit sign not provided Illuminated ISA symbol not provided (MAAB)	- -	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. When the exit sign is replaced with a new illuminated exit sign, provide an illuminated International Symbol of Accessibility (ISA).	1	432	\$432
17	Memorial Egress	1		Means of Egress	N/A		Tactile exit sign not provided Directional sign to accessible emergency exit not provided	- -	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. Provide a directional sign indicating the location of the nearest accessible emergency exit.	1	464	\$464
Doors, Doorways, & Gates												
18	World Languages Room	2		Doors, Doorways, & Gates	Other		Maneuvering clearance(s) not provided	9"	Relocate the sofa to provide 18" min. maneuvering clearance on the pull side of the door.	1	Labor	\$0
19	Women's Toilet Room	3		Doors, Doorways, & Gates	Toilet Room		Maneuvering clearance(s) not provided	-	Relocate the trash can to provide 18" min. maneuvering clearance on the pull side of the door.	1	Labor	\$0
20	Women's and Men's Toilet Room	3		Doors, Doorways, & Gates	Toilet Room		Door requires > 5 lbs. of force to open	16	Adjust closers so doors do not require more than 5 pounds of force to open.	2	Labor	\$0

**Town of Randolph
Turner Free Library**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Signage												
21	Limited Use Limited Application (LULA) Elevator	1		Signage	Informational		Raised characters not provided on sign Braille not provided on sign Sign not located on the latch side of the door	- - -	Provide text with raised characters duplicated in braille on sign. Locate the sign at permanent rooms alongside the door on the latch side.	1	232	\$232
22	Girls' and Boys' Toilet Rooms	1		Signage	Designation		International Symbol of Accessibility (ISA) not correct for toilet rooms		Remove sign with International Symbol of Accessibility (ISA) at these boys' and girls' toilet rooms as they are not accessible.	1	-	\$0
23	Girls' and Boys' Toilet Rooms	1		Signage	Designation		Directional sign to access toilet not provided International Symbol of Accessibility (ISA) not correct for toilet rooms	-	Install a sign indicating the location of the nearest accessible toilet room. (These toilet rooms have doors that are just 27" wide, and they lack the minimum required turning space and accessible plumbing fixtures.) Remove sign with International Symbol of Accessibility (ISA) at these boys' and girls' toilet rooms as they are not accessible.	2	232	\$464
Operable Parts												
24	By Teen Room	3		Operable Parts	Clothes Rod/Hooks		Side reach > 54"	65"	Provide a coat hook 48" above the finished floor.	1	150	\$150
Assembly Area												
25	Shurtleff Room	3		Assembly Area	N/A		Assistive listening devices not provided	-	If audible communication is integral to the use of the space, provide an assistive listening system.	1	1214	\$1214

**Town of Randolph
Turner Free Library**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Exterior Benches												
26	Near Main Entrance	Ext.		Exterior Benches	N/A		No accessible route to one bench in area	-	Relocate bench to an accessible route.	1	-	\$0
Toilet & Bathing Rooms												
Lavatory												
27	All Gender Toilet Room	1		Lavatory	N/A		Toe or knee clearances not provided	25"	Provide at least one lavatory with knee and toe clearance positioned for a forward approach.	1	1686	\$1686
Single-User Toilet												
28	All Gender Toilet Room	1		Single-User Toilet	N/A		Flush control not on open side	-	Relocate the flush control to the open side.	1	374	\$374
Toilet Compartment												
29	Women's and Men's Toilet Room	3		Toilet Compartment	Accessible Compartment		Door pull not provided	-	Provide a door pull on each side of the door between 34" to 48" above the finished floor that does not require tight grasping, pinching or twisting of the wrist.	2	70	\$140
Best Practice												

**Town of Randolph
Turner Free Library**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
30	North Main Street Entrance	Ext.			N/A				Recommend providing a larger automatic door opener with a more visible International Symbol of Accessibility (ISA) or providing a larger symbol on the glass part of the door indicating a power door is present.	1	-	\$0
Directional Sign to Nearest Accessible Exit												
31	Memorial Street Egress to Stairs	Ext.		Directional Sign to Nearest Accessible Exit	N/A				Recommend providing text on the required directional sign guiding visitors to the nearest accessible exit that yields wording similar to, "Nearest Accessible Exit at Main Entrance"	1	-	\$0
Glass Manifestations												
32	Study and Meeting Area	2		Glass Manifestations	N/A				Recommend providing manifestation on glass to reduce likelihood of a collision with the glass surface.	1	-	\$0
Power Door Control												
33	Main Entrance	Ext.		Power Door Control	N/A				Recommend painting the International Symbol of Accessibility (ISA) on the automatic door control in a contrasting color to make the control more visible.	1	-	\$0

**Town of Randolph
Turner Free Library**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Public Address System												
34	Shurtleff Room	3		Public Address System	310			-	Recommend, at the suggestion of the head librarian, providing a better public address system throughout the library.	1	-	\$0
Staircase												
35	Stairs From Floors 1 to 2	1		Staircase	N/A				Recommend providing contrasting color strips at the edge of each step at all stairs.	1	-	\$0